
BAJA KARBON (CARBON STEEL)

Materi Kuliah Bahan Teknik


Definisi

 Baja karbon adalah material logam yang terbentuk dari unsur utama Fe dan unsur kedua yang berpengaruh pada sifat-sifatnya adalah karbon, sedangkan unsur yang lain berpengaruh menurut prosesntasenya.

Diagram Phasa Fe-C




Photomicrographs of (a) ferrite and (b) austenite



Fasa yang terbentuk pada baja karbon

- α Ferrit , or α iron, has a BCC crystal structure at room temperature
- austenite, or γ iron, at 912 °C(1674 °F), has a FCC crystal structure.
- δ **ferrite**, which finally melts at 1538 °C (2800 °F), has a BCC crystal structure
- cementite (Fe3C), extends only to 6.70 wt% C; at this concentration the intermediate compound iron carbide

Klasifikasi bahan Logam



Kalsifikasi Baja Karbon

- Low-Carbon Steels , have contain less than about 0.25 wt% C
- Medium-Carbon Steels, have carbon concentrations between about 0.25 and 0.60 wt%.
- High-Carbon Steels, normally having carbon contents between 0.60 and 1.4 wt%,

Sifat-sifat Baja Karbon

Low Carbon Steel

- relatively soft and weak but have outstanding ductility and toughness; in addition, they are machinable, weldable, and, of all steels, are the least expensive to produce.
- Typical applications include automobile body components, structural shapes (I-beams, channel and angle iron), and sheets that are used in pipelines, buildings, bridges, and tin cans.
- have a yield strength of 275 MPa (40,000 psi), tensile strengths between 415 and 550 MPa (60,000 and 80,000 psi), and a ductility of 25%EL.

Medium Carbon Steel

- The plain medium-carbon steels have low hardenabilities and can be successfully heat treated only in very thin sections and with very rapid quenching rates
- Additions of chromium, nickel, and molybdenum improve the capacity of these alloys to be heat treated, giving rise to a variety of strength-ductility combinations.
- Applications include railway wheels and tracks, gears, crankshafts, and other machine parts and highstrength structural components calling for a combination of high strength, wear resistance, and toughness.

High Carbon Steel

- the hardest, strongest, and yet least ductile of the carbon steels
- always used in a hardened and tempered condition and, as such, are especially wear resistant and capable of holding a sharp cutting edge
- utilized as cutting tools and dies for forming and shaping materials, as well as in knives, razors, hacksaw blades, springs, and high-strength wire